

Firmware Update for the MDK-C5 Keypads

This document provides a comprehensive summary of the Firmware Update

MDK-C5 Firmware 7.03.01

Recommended for:

- All MDK-C5 installations
- Any customers who desire to eliminate screen illumination completely while in the off state
- Anyone using Bluetooth with new MCA-66 and MCA-88 controllers in order to get the updated Bluetooth screen with a larger Bluetooth logo.

New Features:

- New Bluetooth screen with large Bluetooth logo

Bug Fixes:

- LDC screen had a backlight glow when turned off
- SRC-5 (USRC) remote control was able to access the Pandora Options menu
 - This is not supported and was removed since there was nothing that could be done once in the menu

Known Issues:

- MCA-66 and MCA-88 firmware versions 1.X may occasionally display the previous Bluetooth image. Firmware Versions 2.X or higher will consistently display the proper Bluetooth image.
- Saving a Pandora station as F1 or F2 will display “Pandora” instead of the station name in the title bar field
- Spotify title shown in the station field and “PAUSE” hides this name while in that state
- Help text for adding a System Favorite says “Numbers” instead of “Characters” and mentions “use scroll” which does not apply

Current Firmware files are available through SCS-C5 or from our support center at:

www.russound.com