



Firmware Update for the TCH-1 RNET Touchpoint

This document provides a summary of the TCH-1 Firmware Update

Recommended for:

All RNET installations using Touchpoint controlled by iOS 7 software devices, iPhone, iPad, iPod touch

Changes from Previous Release:

TCH-1 communications and control from iOS 7 software devices to RNET devices

Release Notes

Version: 2.02.03

Date: 4/10/2014

Affected products: TCH1

Added / Deleted / Modified Features / Bug Fixes:

17706 --- Will not scroll zone list

Known Problems / Issues / bugs assigned to future release:

- 12191 --- A highlight and delay is needed when selecting sources or zones
- 12433 --- TCH1 does not allow for selecting of Front A/V (Source 7) on CAV6.6
- 12996 --- Volume Up command is sent with 4th numeric entry
- 13239 --- Add "Keep Alive" option to TCH1 software for WiFi
- 13985 --- Add Direct Bank Selection to Tuners
- 14162 --- ENHANCEMENT: Add RDS info for capable tuners

TCH1 Release Notes

Version: 2.02.02

Date: 3/20/2014

Affected products: TCH1

Added / Deleted / Modified Features / Bug Fixes:

17637 --- TCH1 does not work with iOS7

Known Problems / Issues / bugs assigned to future release:

- 12191 --- A highlight and delay is needed when selecting sources or zones
- 12433 --- TCH1 does not allow for selecting of Front A/V (Source 7) on CAV6.6
- 12996 --- Volume Up command is sent with 4th numeric entry
- 13239 --- Add "Keep Alive" option to TCH1 software for WiFi
- 13985 --- Add Direct Bank Selection to Tuners
- 14162 --- ENHANCEMENT: Add RDS info for capable tuners

Detailed instructions for updating the TCH-1 and current firmware files are available from our support site at www.russound.com