Firmware Update for the TS3 Touchscreen UI

This document provides a comprehensive summary of the Firmware Update

TS3 Firmware 7.00.00

Recommended for:

- All TS3 installations

New Features:

- N/A

Bug Fixes:

- Flash correction being reported in the field
  - The screen would go blank or have lines displayed and the TS3 would be rendered non-functional



Known Issues:

- While using Spotify, an option for 'Repeat –Single Track' will display in the Repeat menu, but this option is not supported by Spotify. Instead of being in Repeat-Single Track, the player will actually be in Repeat All mode.
- If you are in the Streamer Home menu while a Page occurs, the screen will return to a blank list. This issue can be easily resolved by navigating away from the page momentarily.

Current Firmware files are available through SCS-C5 or from our support center at:
www.russound.com