



E-Series Release 4 Information

New Hardware for E-Series Release 4

RFR-E5 Radio Frequency Remote Control

New Software Features for E-Series Release 4

ACA-E5

- The ACA-E5 Internal FM Tuner and the AFM module now support RDS information provided by the radio station.
- The UNO-S1 keypad will now control a zone. Clock and sleep timer functions, as well as the 32 global favorites will not be available from the UNO-S1.

TSV-E5

- Improved overall performance.
- Improved IP Camera performance.
- Remote Zone Control.

SCS-E5

- System Check – View firmware versions for controllers, user interfaces and connected RNET devices.
- Device Update – Allows the ACA-E5 Co-processor and KLK-E5 keypads to be updated through the ACA-E5.

Resolved Issues

- The HHR-E5 Sleep Button will scroll through the sleep timer option via the KLK-E5 Keypad.
- TSV-E5 Hard button will provide source and volume adjustments while using a web widget.
- A zone will return to MUTED after a doorbell event.
- Source Linking is now supported on slave controllers.

SQA Known Issues Report

SCS-E5

BUG: 13507

The System check output has no scroll bar to scroll down to the bottom of the list in large E-Series Systems.

Work around - Selecting an item in the list and using the down arrow key will allow you to see the items at the end of the list.

TSV-E5

BUG: 13304

The IP camera video player may cause the IP camera image to display over or behind the system bar.

Work around - Refreshing the screen or scrolling the IP camera widget away from the bottom of the screen should resolve this.

BUG: 13422

(continued on next page)

Sphere Technical Support: 1-866-604-5245 M - F 8:30 a.m. - 7 p.m. EST



SPHERE™

Premier products for Russound-
SPHERE™ Certified Professionals

The Sphere Certified Integrator Program is a premium service program for experienced multiroom audio and video dealers. For more information on the Sphere program please visit www.russoundsphere.com

Russound

USA 603.659.5170

5 Forbes Road, Newmarket, New Hampshire 03857

www.russound.com

©2009 Russound. All rights reserved. All trademarks are the property of their respective owners. Specifications are subject to change without notice. Russound is not responsible for typographical errors or omissions. JE kaw 11/09/09

E-Series Release 4 Information (continued)

The TSV-E5 does not respond to the HHR-E5 SLEEP button.

Work around - To set the SLEEP timer on the TSV-E5 go to the system screen.

BUG: 13464

When a preset is deleted from a tuner on the TSV-E5, the preset is deleted; however, if viewed on a KLK-E5 or RFR-E5, the preset name will still be in the list.

Work around - Overwrite the preset with something new, or use SCS-E5 to remove the name.

BUG: 13465

The first IP camera configured on a TSV-E5 will automatically be set as the IP camera to display for Doorbell 1 or Doorbell 2 event.

Work around - After configuring the IP camera go into the Doorbell Config on the TSV-E5 and set the desired IP camera to use or set each doorbell to "None."

BUG: 13449

A TSV-E5 cannot open a Support Tunnel if it is configured for a slave controller

Work around - Open a support tunnel on a KLK-E5 or a TSV-E5 configured for a zone on controller 1.

BUG: 13325

The TSV-E5 Remote Zone Control option will allow a user to manipulate a Zone that is a Party Master or in DND.

RFR-E5

BUG: 13497

If an RFR-E5 has been used to MUTE a zone and the RFR-E5 goes into standby, the RFR-E5 will not indicate the zone is still Muted.

Work around - Pressing the Volume Up/Down buttons will unmute the zone.

BUG: 13468

If the Search Fwd/Rev buttons are pressed when in the menu for an iBridge Dock or iBridge Bay, the song will fast forward or reverse until it reaches the end/beginning of the song.

KLK-E5

BUG: 13458

If during the ACA-E5's start up the Power Button is pressed on the KLK-E5, the KLK-E5 may end up in an unresponsive state.

Work around - Power cycle the ACA-E5 controller and do not attempt to power a keypad until the ACA-E5 is completely powered up.