



Using Russound Devices with E-Series Products

Legacy RNET Device	Supported by ACA-E5?	Minimum Firmware Requirements	Notes
Source Equipment			
ST2-XM Tuner	Y	4.01.00 chassis firmware 4.00.13 XM firmware	FW upgrade requires DB9 serial cable FW upgrade requires Prog. Cable 2500-121036
ST2-XM2 Tuner	Y	4.01.00 chassis firmware 4.00.13 XM firmware	FW upgrade requires DB9 serial cable FW upgrade requires Prog. Cable 2500-121036
ST2 Tuner	Y	4.01.00 chassis firmware	FW upgrade requires DB9 serial cable
ST2S Tuner	Y	4.01.00 chassis firmware 3.00.16 SIRIUS firmware	FW upgrade requires DB9 serial cable FW upgrade requires Prog. Cable 2500-121036
SMS3 Media Server	Y	03.01.01	Available via online update
VM1 Video Matrix	Y	1.00.01	FW upgrade requires DB9 serial cable
VM1 Video Matrix (controller 2)	Y	1.00.00	FW upgrade requires DB9 serial cable
BGD1/BGK1 iBridge Dock	Y	2.00.04	FW upgrade requires Prog. Cable 2500-521065
BGD2/BGK2 iBridge Bay	Y	2.00.05 Application 1.00.01 Firmware	Online update in application
BGK3 iBridge Powerline Dock	N		TBD
Touchscreens/Keypads			
UNO-TS2 Touchscreen	Y	3.00.02 screens version 1.66 firmware	FW upgrade requires Prog. Cable 2500-121036 FW upgrade requires Prog. Cable 2500-121036
UNO-S2	N		Not compatible with ACA-E5
UNO-S1	Y	2.00.01	FW upgrade requires Prog. Cable 2500-521065

All current firmware update files are located on the Russound Document Center (www.russound.com/doccenter/doccenter.php) and Sphere Portal (www.russoundsphere.com/dealerhome.html).

Sphere Technical Support: 1-866-604-5245 M - F 8:30 a.m. - 7 p.m. EST



SPHERE™

Premier products for Russound-SPHERE™ Certified Professionals

The Sphere Certified Integrator Program is a premium service program for experienced multiroom audio and video dealers. For more information on the Sphere program please visit www.russoundsphere.com



USA 603.659.5170
©2009 Russound. All rights reserved. All trademarks are the property of their respective owners. Specifications are subject to change without notice. Russound is not responsible for typographical errors or omissions.

5 Forbes Road, Newmarket, New Hampshire 03857
www.russound.com
kaw 01/13/10